

P.S. STRETCH

Description

PVC-free material for Cad-Cut® applications.

The material is very thin and soft to the hand and blends well in textiles. It has great stretch-and-rebound properties.

It guarantees easy weeding and application.

Backing: **adhesive polyester**.

Basic Information

Due to the many different base materials available on the market, the following heat transfer instructions are given as guideline only:

Temperature: 155°C

Time: 15"

Pressure: medium-high (about 4 bar)

Application Instructions

- 1) Cut the material **in reverse**
- 2) Weed the exceeding material (for an easier weeding, we suggest to leave the cut material on a hot surface for a few seconds)
- 3) Place the material on the garment with its polyester support
- 4) Heat apply
- 5) Remove polyester backing **hot or cold**

Suitable for

Cotton, polyester, Lycra and blends.

Not suitable for treated and dyed garments (sublimation inks)

Washing: (wait 24h after the heat transfer)

60°C Max. – do not use bleach or other aggressive chemical agents

Dry-cleaning : no

Tumble drier : yes

N.B. : all information given in this sheet are based on our experience

We recommend to always perform a test before starting standard production

The product meets the Italian and Ue regulations relating to its proper use.

This document can be subject to variations. Updated versions are available on our website www.siser.it.

For further information, please contact our Sales Office. Thank you.

SISER s.r.l.

V.LE DELLA TECNICA n. 18 – 36100 VICENZA ITALY

TEL. +39 0444 287960 - FAX +39 0444 287959 - E-mail: info@siser.it - www.siser.it

R.E.A. VI 171856 VI – Reg. Imp. VI n. 14971 - Cap. Soc. € 103.300 i.v. – Partita IVA 01591490246



Organizzazione con sistema di gestione certificato
ISO 9001:2008